## APPNENDIX - XI

## **BUILDING SAFETY CERTIFICATE**

No.

Dated: <u>63</u> - 62 - 2023

Certified that the existing building 1- Primary (G + 2) 2- Eastern Building (G + 2) 3- Western Building
(G+2) 4- New Building (G + 4) (name of the building or premises) at Glenhill School, Manduadih,
Varanasi, U.P. PIN 221103. (address) comprised of
basement(s) and (67.4) as detailed above (upper floors)
owned/occupied byGlenhill School, Manduadih, Varanasi, U.P. (name of the Institution) have complied
with the Building safety requirements in accordance with National Building code Rules, and verified by the
officers concerned of Works Deptt. (PWD) Varanasi (Name of Department/ Govt.)
on. 03-02-2023 (date of inspection) in the presence of Mr. C. P. Singh Plot No. 509/1, Lalpur,
Meerapur, Basahi, Varanasi, Phone No. 9415295454 (name and addresses of the Manager / Secretary
or his representative ) and that the building / premises is fit for occupancy upto classes $XII^{th}$ (X / XII)
with effect from 03 02 2023 for a period of FIVE Three years in
accordance with rule and subject to compliance of the specific conditions as appended.

- 1.

3.

4.

\* Strike out whichever is not applicable.

Signature with Seal भान्तीय खरह, लोकनिवदिः,

वाराणसी। Name :

Designation : Assistant Enga

Name & Address of Department/ Office: \_\_\_\_

(Assistant Engineer & above officer of concerned Govt. Department only)

Note: This certificate should be signed / issued by Assistant Engineer & above officer of concerned Govt. Department only

\* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.

OOL VDIH ST-221103

쓶

For GLENHILL SC HOOL RETARY